## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


## IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.




PROVIDING FIBER BUNDLE A SZOZ Cuthing FBERBUNDLE INTO Sheets OF FIBER BUNDLE SEMONTS MODIFING ENDS OF FIBER -5206 BUNDLE SEEMONTS Exposing FIBOR BUNDLE ENDS TO A ROPETUE LIQUID TOFORM COMME THE TIPS WITH A CONDUCTIVE MATERIAL F16. 2 DEPOSITING A DIELEZAMIC/25212 LAVER FORMING A GATE ELEZTRADE IL SZ14 tr 5216 Removing Portions OF THE DIELECTRIC LINIER TO EXPOSE THE COMED TIPS








F16.7





. . . . .

